
I.

II.



355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

Gener	ral Information
1.	Report Time Period: From (mo./yr.) OCT 94 To (mo./yr.) 30 SEPT 95
2.	DOGM File Number (Mine No): 1/027/032
3.	Mine Name: RED DOME
4.	Mineral(s) Mined (or permitted to mine):
5.	Type of mine Surface Mine or Underground Mine
6.	Legal Description (Location of Lands Affected):
	1/4,1/4, Section <u>26</u> , Township <u>2150</u> , Range <u>6 WEST-SLBASE</u>
	1/4,1/4, Section 23, Township, Range
	1/4,1/4, Section 27, Township, Range
7.	Name of Operator or Company: RED DOME INC
8.	Permanent Street Address: 5900 WEST 200 SO.
	City, State, Zip: FILL MORE UT 84631
	Phone: 801-7592633
9.	Company Representative (or designated operator):
	Name: DEXTER ANDERSON
	Title: LEGAL REGENTATIVE
	Business Address: RED DOME INC
	City, State, Zip: STAR ROUTE BOX52 FILLHURE UT 84631
	Phone: 701-743 6677
	Please check if any of the above information has changed since previous year.
Mining	g and Reclamation
IVIIIIII	g and Recialitation
1.	Was the mine active during the past year? Yes ☑ No □
2.	If active, how much ore or mineral was mined? 24,370 TOWS

	3.	How much additional acreage was disturbed during the past year?NONE
	4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
		NONE
5.		How much acreage was reclaimed during the past year? MBOUT FIVE ARES
6.		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. THE SOUTHERN SECTION WAS ABANDONED AS TO
		CINIDER REMOVAL. AVAILHBUE TOP SOIL W43 ROUGHAY
		SPREAD ACCORDING TO METHOD SUGGESTED BY YOUR
	,	DEPT TITEM SEEDED WITH HOFSERT MIX-RESULTS-PROGRESSING SLOWLY
7.		What is the total disturbed acreage at years end? ACRES
8.		Briefly summarize any mining and/or reclamation plans for the upcoming year.
		NONE ANTICIPATED -
NOTE:		Section III., "Additional Information" applies only to large mining operations.
III. Addit	iona	<u>Information</u>
1.		An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2.		Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. Signa	ature	Requirement
r 1	heret	by certify that the foregoing is true and correct.
		Name (Typed or Print):
		Title of Operator: PRES.
		Signature of Operator: Signature of Operator: Signature of Operator:
		Date: 2579N 960